



---

# DET NORSKE VERITAS

---

## MANAGEMENT SYSTEM CERTIFICATE

---

Certificate No. 106933-2011-AQ-ARG-RvA

*This is to certify that*

### **Acindar Grupo ArcelorMittal**

*Address*

Ruta Provincial 21 Km. 247, N° 4855 - S2919GBC Villa Constitución - Provincia de Santa Fe República Argentina

*and other Sites and Child Certificates listed in the Supplement to this Certificate*

*has been found to conform to the Management System Standard:*

**ISO 9001:2008**

*This Certificate is valid for the following product or service ranges:*

**PRODUCTION, SALE, DISTRIBUTION AND TECHNICAL ASSISTANCE OF  
STEEL PRODUCTS INDUSTRY, AGRO AND CONSTRUCTION.**

**PRODUCCIÓN, COMERCIALIZACIÓN, DISTRIBUCIÓN Y ASISTENCIA TÉCNICA DE PRODUCTOS  
SIDERÚRGICOS PARA LA INDUSTRIA, EL AGRO Y LA CONSTRUCCIÓN.**

*Initial Certification Date:*  
22 December 2011

---

*Place and Date:*  
Buenos Aires, 22 December 2011

---

*This Certificate is Valid Until:*  
22 December 2014


---

*for the Accredited Unit:*  
DET NORSKE VERITAS CERTIFICATION B.V.,  
THE NETHERLANDS

*The audit has been performed  
under the supervision of:*

---

**Luis Rodriguez**  
*Lead Auditor*

  
**Julio Raúl Martinoli**  
*Operations Manager*

---

Lack of fulfilment of conditions as set out in the Certification Agreement may render this Certificate invalid.



# DET NORSKE VERITAS

## SUPPLEMENT TO CERTIFICATE

This Supplement pertains to Certificate No. 106933-2011-AQ-ARG-RvA

### Acindar Grupo ArcelorMittal

Locations included in the certification are as follows:

| Site Name   | Address                                    | City               | State        | Country   |
|---|--|--------------------|--------------|-----------|
| Planta Complejo Industrial Villa Constitución             | Ruta Provincial 21 Km. 247, Nro 4855       | Villa Constitución | Santa Fe     | Argentina |
| Planta Mallas Especiales                                  | Ruta Nacional Nro. 7 Km. 703               | Villa Mercedes     | San Luis     | Argentina |
| Planta Complejo Industrial La Tablada                     | Dr. Ignacio Arieta 4936                    | La Tablada         | Buenos Aires | Argentina |
| Planta Aceros Largos Rosario                              | Av. Presidente Perón 8000                  | Rosario            | Santa Fe     | Argentina |
| Planta Mallas y Clavos                                    | Ruta Nacional 148 Km. 756                  | Villa Mercedes     | San Luis     | Argentina |
| Sede Corporativa  | Estanislao Zeballos 2739                   | Beccar             | Buenos Aires | Argentina |
| Planta Enderezado, Acondicionado y Centro de Distribución | Boulevard Seguí 7326                       | Rosario            | Santa Fe     | Argentina |
| Planta Aceros Largos San Nicolás                          | Paraná 1                                   | San Nicolás        | Buenos Aires | Argentina |
| Planta Perfiles Livianos San Nicolás                      | Av. Rucci 799                              | San Nicolás        | Buenos Aires | Argentina |
| Centro de Distribución Villa Mercedes                     | Ruta Interfábricas 2b, Frente al Golf Club | Villa Mercedes     | San Luis     | Argentina |

Initial Certification Date:  
22 December 2011

Place and date:  
Buenos Aires, 22 December 2011

This Certificate is Valid Until:  
22 December 2014

The audit has been performed  
under the supervision of:

Luis Rodriguez  
Lead Auditor



for the Accredited Unit:  
DET NORSKE VERITAS CERTIFICATION B.V.,  
THE NETHERLANDS

Julio Raúl Martinoli  
Operations Manager

Lack of fulfilment of conditions as set out in the Certification Agreement may render this Certificate invalid.



# DET NORSKE VERITAS

## SUPPLEMENT TO CERTIFICATE

This Supplement pertains to Certificate No. 106933-2011-AQ-ARG-RvA

### Acindar Grupo ArcelorMittal

Locations included in the certification are as follows:

| Child Certificate Number  | Site Name                 | Site Address   | Site Scope  |
|---------------------------|---------------------------|--|---|
| 106933CC1-2011-AQ-ARG-RvA | INDUSTRIAL<br>SIDERÚRGICO | Ruta Provincial 21<br>Km. 247, Nro 4855<br>Villa Constitución , Santa Fe | PRODUCTION, SALE,<br>DISTRIBUTION AND<br>TECHNICAL ASSISTANCE OF<br>STEEL PRODUCTS INDUSTRY,<br>AGRO AND CONSTRUCTION |
| 106933CC2-2011-AQ-ARG-RvA | ALAMBRES                  | Dr. Ignacio Arieta 4936<br>La Tablada, Buenos Aires                      | PRODUCTION, SALE,<br>DISTRIBUTION AND<br>TECHNICAL ASSISTANCE OF<br>STEEL PRODUCTS INDUSTRY,<br>AGRO AND CONSTRUCTION |
| 106933CC3-2011-AQ-ARG-RvA | COMPRAS Y LOGÍSTICA       | Ruta Provincial 21<br>Km. 247, Nro 4855<br>Villa Constitución , Santa Fe | PRODUCTION, SALE,<br>DISTRIBUTION AND<br>TECHNICAL ASSISTANCE OF<br>STEEL PRODUCTS INDUSTRY,<br>AGRO AND CONSTRUCTION |
| 106933CC4-2011-AQ-ARG-RvA | COMERCIAL<br>SIDERÚRGICO  | Estanislao Zeballos 2739<br>Beccar, Buenos Aires                         | PRODUCTION, SALE,<br>DISTRIBUTION AND<br>TECHNICAL ASSISTANCE OF<br>STEEL PRODUCTS INDUSTRY,<br>AGRO AND CONSTRUCTION |

Initial Certification Date:  
22 December 2011

Place and date:  
Buenos Aires, 22 December 2011

This Certificate is Valid Until:  
22 December 2014

The audit has been performed  
under the supervision of:

Luis Rodriguez  
Lead Auditor



for the Accredited Unit:  
DET NORSKE VERITAS CERTIFICATION B.V.,  
THE NETHERLANDS

Julio Raúl Martinoli  
Operations Manager

Lack of fulfilment of conditions as set out in the Certification Agreement may render this Certificate invalid.